Product Safety Recall

Septone MEKP Catalyst 20ml and Septone Fibreglass Repair Kit

Sold 1 July 2020 - 27 August 2020

at various automotive accessories, paint, hardware and marine supplies stores.

MEKP Catalyst

Fibreglass Repair Kit

Product code - MMEKP20   Product code - ABFR2
Batch number - LF09742

Defect: Products can leak from the cap of the MEKP Catalyst bottle.

Hazard: Leaking product is flammable and may cause skin and/or eye irritation.

What to do: Consumers should immediately contact ITW for further information about handling and storing the products, and to arrange for the products to be collected and for a full refund or store credit to be issued.

Contact details: For further information and to arrange collection, phone 1800 177 989 or email sales@aamtech.com.au

See productsafety.gov.au for Australian product recall information