

# Product Safety Recall

## Bosch / ACDelco Brake Disc Rotor



Part number 0986479V29 with manufacturing dates from January 2017 - August 2019 (numbers 717 - 956)

Ⓟ BOSCH 0 986 479 V29 MIN. TH. 25.0 (250) [25A] 853241591

Part Number: 0 986 479 V29



Manufacture code identification: 717 to 956



Sold by Robert Bosch (Australia) Pty Ltd  
Sold between 1 March 2017 and 9 February 2019  
Designed to be fitted on the front axle of select Holden Colorado and Isuzu D-Max models manufactured from 2011.

### Defect:

Due to improper manufacturing, the brake disc rotor hub wall may not be thick enough in the neck area, which may crack.

### Hazard:

If the brake disc rotor hub cracks, the vehicle could experience reduced braking capacity which may increase the risk of an accident or injury to vehicle occupants and/or other road users.

### What to Do:

Consumers should immediately stop using the affected products, or vehicles that have been fitted with an affected product, and contact the place of purchase for instructions on obtaining a replacement or refund.

### Contact Details:

For more information, contact Robert Bosch (Australia) Pty Ltd on 1800 025 462, or via their email: [BoschService.NetworkWebsiteEnquiry@au.bosch.com](mailto:BoschService.NetworkWebsiteEnquiry@au.bosch.com)

See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information