


# Product Safety Recall



**SCA Hydraulic Trolley Jack 2000kg**  
Sold at Supercheap Auto stores from 25/10/2019 to 3/7/2020.

**Product Description:** Trolley jack in red colour. PLU 563847.  
The batch number is located on the top of the lift arm assembly.  
Only batches with the following batch numbers:

4511430656, 4511430657, 4511430658, 4511483271, 4511483273, 4511483839,  
4512224615, 4512224629, 4512224631, 4512224639, 4512224650, 4511575065 or  
4511575069 are affected.

**Defect:** The trolley jack does not comply with the durability requirements of the Consumer Goods (Trolley Jacks) Safety Standard 2017. The lift piston may seize during use

**Hazard:** If the lift piston seizes during use of the trolley jack, the jack will no longer be able to be used to lift a vehicle. The trolley jack should be carefully lowered in the normal way to avoid injury and removed from the vehicle.

**What to do:** Consumers should immediately stop using the product and return the products to their nearest Supercheap Auto store for a full refund.

**Contact Details:** You can contact Supercheap Auto customer care centre on 1300 175 010, Monday to Sunday (9am to 4pm AEST) or see its website on <https://www.supercheapauto.com.au>

**See [productsafety.gov.au](https://productsafety.gov.au) for  
Australian product recall information**